

**Exhibit A
Village of Oak Park
Equipment Replacement Analysis**

11/16/2015

Vehicle #	Year	Make	Model	Mileage	VIN #	Purchase Date	Original Purchase Price	Current Trade-in Value	Fuel	Repairs and Regular Maintenance (includes parts, labor and fluids)	Combined Total Costs
173	2009	FORD	CROWN VIC	35495	2FAHP71V89X101471	9/30/2008	\$ 21,798.00	WRECK	\$26,392.17	\$25,826.21	\$52,218.38
232	2012	DODGE	CHARGER	9256	2C3CDXAG5CH215268	3/12/2012	\$ 24,179.00	WRECK	\$7,057.65	\$8,688.08	\$15,745.73
30	2001	CHEVY	IMPALA	35872	2G1WF55K019372406	8/3/2001	\$ 21,294.00	\$ 500.00	\$6,982.27	\$22,618.80	\$29,301.07
751	1998	GREEN	414RS	1553 HR	804894	7/8/1998	\$ 25,946.00	\$ 100.00	\$279.06	\$23,402.75	\$23,681.81
963	1988	BILLY	BILLYGOAT	N/A	112805231			\$ -			\$0.00
											\$0.00
											\$9,765.18

DEPT	EQUIPMENT	QTY	EXPLANATION
FIRE	Obsolete 2 way radios	16	Obsolete handheld radios
FLEET	VAT 45 Charging/Starting tester	1	Not functioning. Repair exceeds replacement
PARKING	Parking Meter Heads	212	Worn out or displaced
PARKING	Tall jack stands	50	Project completed
PARKING	Granite blocks	1125	Not utilized

Obsolete	
Handheld 2 way radios	
MOTOROLA VERTEX	
Ser#	
71280121	
71280123	
71280124	
71280125	
71280134	
71280139	
71280185	
71280187	
71280192	
71280195	
71280196	
71280197	
77280193	
80350196	
80350198	
81400424	