| Project No. 17-9 Watermain Valve Replacements              |           |               |         |            |             |               |                 |
|--|-----------|---------------|---------|------------|-------------|---------------|-----------------|
|  |           |               |         |            |             |               | 10/14/2017      |
| COMPANY NAME   | MBE       | WBE           | DBE     | NON        | As-Read Bid | Corrected Bid | Notes:          |
| Cerniglia Co.  |           |               |         | Х          | \$87,194.00 | \$87,194.00   |                 |
| Tyson Plumbing   |           |               |         |            |             |               | Note #3         |
| Gerardi Sewer and Water Co.                                |           |               |         |            |             |               | Note #3         |
| J. Congdon Sewer Service, Inc.                             |           |               |         |            |             |               | Note #3         |
| Unique Plumbing  |           |               |         | х          | \$53,160.00 | \$79,410.00   | Lowest bidder   |
| Martam Construction, Inc.                                  |           |               |         |            |             |               | Note #3         |
| Copenhaver Construction                                    |           |               |         |            |             |               | Note #3         |
| Note # 1 = Package was returned with                       | out a fow | <br>/arding a | address | j.         |             |               |                 |
| Note # 2 = Company could not complete the package in time. |           |               |         |            |             |               |                 |
| Note # 3 = Company was not interested in the project.      |           |               |         |            |             |               |                 |
| Note # 4 = Company was disqualified                        |           |               |         | •          |             |               | ·               |
| Note #5 = Company had prior commit                         | ments and | d could       | not mee | et time so | hedule      |               |                 |
| Note #6= Sub-contractor not bidding as Prime Contractor    |           |               |         |            |             |               |                 |
|  |           |               |         |            |             |               | 9/14/2017 11:01 |